

APPENDIX H. SITE PHOTOGRAPHS

List of Photographs

<i>Photo 1. Mussels on pilings of cement plant at RM 1.5 upstream of Kellogg Is. Photo taken during initial reconnaissance survey, July 16, 2003.</i>	4
<i>Photo 2. Mussels on pilings in slip 4 (RM 2.9). Photo taken during initial reconnaissance survey, July 16, 2003.</i>	4
<i>Photo 3. Mussels on pilings of the 16th Avenue Bridge (RM 3.3). Photo taken during initial reconnaissance survey, July 16, 2003.</i>	5
<i>Photo 4. Clam sampling gear at beach 8, August 8, 2003.</i>	5
<i>Photo 5. Setting the baseline at beach 8, August 8, 2003.</i>	6
<i>Photo 6. Setting quadrat locations at beach 8, August, 8, 2003.</i>	6
<i>Photo 7. Measuring the elevation at the top of the sample area at beach 8, August 8, 2003.</i>	7
<i>Photo 8. An excavated quadrat at beach 1a (T105), August 8, 2003.</i>	8
<i>Photo 9. An excavated quadrat at beach 1a (T105), August 8, 2003.</i>	8
<i>Photo 10. Completed quadrats on beach 8, August 8, 2003.</i>	9
<i>Photo 11. Clams (macoma spp.) collected at quadrat 7 on beach 8, August, 8, 2003.</i>	9
<i>Photo 12. Setting the baseline at beach 7, August 9, 2003.</i>	10
<i>Photo 13. Setting quadrat locations at beach 7, August 9, 2003.</i>	10
<i>Photo 14. Measuring the elevation at the top of the sample area at beach 7, August 9, 2003.</i>	11
<i>Photo 15. Excavating quadrats at beach 7, August 9, 2003.</i>	11
<i>Photo 16. Excavating quadrats at beach 7, August 9, 2003.</i>	12
<i>Photo 17. Collecting sediment cores for interstitial salinity and percent fines measurements at beach 7, August 9, 2003.</i>	12
<i>Photo 18. Setting transects at beach 13a, August 9, 2003.</i>	13
<i>Photo 19. Setting transects at beach 13a, August 9, 2003.</i>	13
<i>Photo 20. Quadrat location at beach 13a, August 9, 2003.</i>	14
<i>Photo 21. Setting baseline at beach 16, August 10, 2003.</i>	14
<i>Photo 22. Setting transects at beach 16, August 10, 2003.</i>	15
<i>Photo 23. Excavating quadrats at beach 16, August 10, 2003.</i>	15
<i>Photo 24. Survey set-up at beach 16, August 10, 2003.</i>	16
<i>Photo 25. Setting baseline at beach 2a (Kellogg Island mainland), August 12, 2003.</i>	16

- Photo 26. Excavating quadrats at beach 2a (Kellogg Island mainland), August 12, 2003.* 17
- Photo 27. Harvesting clams for CPUE survey at beach 1a (T105), August 13, 2003.* 17
- Photo 28. Shorecrab (Hemigrapsus spp.) found on beach 1a (T105) during the CPUE survey, August 13, 2003.* 18



Photo 1. Mussels on pilings of cement plant at RM 1.5 upstream of Kellogg Is. Photo taken during initial reconnaissance survey, July 16, 2003.



Photo 2. Mussels on pilings in slip 4 (RM 2.9). Photo taken during initial reconnaissance survey, July 16, 2003.



Photo 3. Mussels on pilings of the 16th Avenue Bridge (RM 3.3). Photo taken during initial reconnaissance survey, July 16, 2003.



Photo 4. Clam sampling gear at beach 8, August 8, 2003.



Photo 5. Setting the baseline at beach 8, August 8, 2003.



Photo 6. Setting quadrat locations at beach 8, August, 8, 2003.



Photo 7. Measuring the elevation at the top of the sample area at beach 8, August 8, 2003.



Photo 8. An excavated quadrat at beach 1a (T105), August 8, 2003.



Photo 9. An excavated quadrat at beach 1a (T105), August 8, 2003.



Photo 10. Completed quadrats on beach 8, August 8, 2003.



Photo 11. Clams (*macoma* spp.) collected at quadrat 7 on beach 8, August 8, 2003.



Photo 12. Setting the baseline at beach 7, August 9, 2003.



Photo 13. Setting quadrat locations at beach 7, August 9, 2003.



Photo 14. Measuring the elevation at the top of the sample area at beach 7, August 9, 2003.



Photo 15. Excavating quadrats at beach 7, August 9, 2003.



Photo 16. Excavating quadrats at beach 7, August 9, 2003.



Photo 17. Collecting sediment cores for interstitial salinity and percent fines measurements at beach 7, August 9, 2003.



Photo 18. Setting transects at beach 13a, August 9, 2003.



Photo 19. Setting transects at beach 13a, August 9, 2003.



Photo 20. Quadrat location at beach 13a, August 9, 2003.



Photo 21. Setting baseline at beach 16, August 10, 2003.



Photo 22. Setting transects at beach 16, August 10, 2003.



Photo 23. Excavating quadrats at beach 16, August 10, 2003.



Photo 24. Survey set-up at beach 16, August 10, 2003.



Photo 25. Setting baseline at beach 2a (Kellogg Island mainland), August 12, 2003.



Photo 26. Excavating quadrats at beach 2a (Kellogg Island mainland), August 12, 2003.



Photo 27. Harvesting clams for CPUE survey at beach 1a (T105), August 13, 2003.



Photo 28. Shorecrab (*Hemigrapsus* spp.) found on beach 1a (T105) during the CPUE survey, August 13, 2003.