



LOWER DUWAMISH WATERWAY UPPER REACH

Cleanup Construction News

LOWER DUWAMISH
WATERWAY GROUP



[Visit our website](#) / [Sitio web](#) / [Trang web](#) / [គេហទំព័រ](#)

Cleanup Construction Activities

Season 2 construction in the upper reach, the southernmost two miles of the Lower Duwamish Waterway Superfund site, will continue through February 2026. Construction will occur on weekdays and Saturdays, with **work taking place during both daytime and, when needed, nighttime hours**. Work hours vary based on factors such as tides and the type of work being conducted (e.g., dredging or placing clean material).

Please note that in-water construction activities are dynamic and weather-dependent. All schedules are subject to change. Visit LDWG.org for the most up-to-date information.

If you have questions, or concerns, you can reach our team at info@ldwg.org or 1-888-561-LDWG (1-888-561-5394).

Map of cleanup areas

Environmental and Community Report for the Week of January 19

View Last Week's Environmental and Community Report



With oversight from the U.S. Environmental Protection Agency (EPA), we are working to minimize the impact of construction on those who work, live, and spend time along the Duwamish Waterway. Stay informed about environmental monitoring and construction activities by viewing our weekly report linked above.

What to Expect During the Week of February 2

Cleanup dredging activities will take place at sediment management area (SMA) **12B** and one area near the shoreline of SMA **9**. We will be placing clean material where dredging was previously completed at SMAs **9** and **16**. Work will occur during the daytime, between 6:30 a.m. and 6 p.m.

What to Expect During the Week of February 9


Cleanup activities will take place at SMAs **9**, **11A**, and **12B**. Most work will occur during the daytime, between 6:30 a.m. and 6 p.m. On a few days, work at SMA 9 will need to occur later, between 11 a.m. and 9 p.m., to align with tidal conditions.

Monitoring for and containing sheens during cleanup activities at SMA 12B

Dredging resumed in SMA 12B on January 21. Some small sheens have been observed and were quickly contained and cleaned up by the Clean Harbors crew using oil-absorbing booms. The construction management team continues to conduct visual inspections for sheens during the dredging of SMA 12B. Clean Harbors continues to be on site to capture and manage any sheens associated with the dredging at SMA 12B.



Dredging at SMA 12B with sheen capture and management equipment actively adjusting to respond to sheen observations (King County, January 23, 2026).



Sheen recovery crews adjusting and maintaining oil-containment booms and bubble curtain used to capture and manage sheens observed as a result of dredging SMA 12B (King County, January 23, 2026).

Stay Connected!

For questions or concerns, you can always reach our team at info@ldwg.org or 1-888-561-LDWG (1-888-561-5394). Visit [LDWG.org](https://www.ldwg.org) for the most up-to-date information.



Visit LDWG website



Send us an email



Visit EPA website

Stay informed during cleanup construction!

Visit our website

Manténgase informado durante toda la actividad de construcción para la limpieza

Sitio web

Cập nhật thông tin trong quá trình thi công để dọn dẹp

Trang web

ទទួលបានការជូនដំណឹងអំឡុងពេលការសាងសង់សម្រាប់ការសម្អាត

គេហទំព័រ

Give us a call at 1-888-561-5394

LDWG | info@ldwg.org | Seattle, WA 98108 US

[Unsubscribe](#) | [Update Profile](#) | [Constant Contact Data Notice](#)



Try email marketing for free today!